



STROJEVI KOJI SE NE POPRAVLJAJU

Tip Stroja	Godina
36 M32	2005
36 M62	2005
AG 125-S	31/01/2015
AG 125-SE	31/01/2015
BP 10	2005
BP 12	2008
BP 40	2006
BP 60	2005
BP 72	2006
CU 10	2005
DAG 115-S	2014
DC 125	2006
DC 125-S	31/01/2015
DC 180-S	2014
DC 230	2006
DCM 1	2004
DCM 1.5	2004
DCM 2	2004
DD 80-E	2005
DD VP7	2006
DC SE 19	2013
DX 350	2009
DX 400	2004
DX 450	2010
DX 600-N	2004
DX 650	2004
DX A70-M	2011
DX A70-R	2011
FS 10	2009
MX 32	2005
MX 62	2005
MX 75	2011
P 2000	2012
P 3000-D	2007
P 5000	2012
P 5000-HY	2012
PD 10	2004
PD 20	2006
PD 22	2007
PD 25	2006
PD 28	2011
PD 30	2012
PD 32	2012
PD 38	31/12/2015
PL 10	2003
PL 10N	2005

Tip Stroja	Godina
PM 10	2005
PM 22	2011
PM 24	2011
PMC 36	31/12/2015
PML 32	2012
PML 32-R	2012
PR 10	2005
PR 15	2006
PR 16	2011
PR 20	2014
PR 25	31/12/2015
PR 50	2005
PR 60	2007
PS 20	2011
RB 10	2008
SB 10	2004
SB 12	2004
SBC 12H	2005
SBC 12M	2004
SBP 12	2010
SD 45	2011
SF 120-A	2008
SF 150-A	2012
SF 180-A	2014
SFB 125	2008
SFC 7/18	2012
SFC 7/18-H	2012
ST 18	2010
TAD 500	2013
TB 12-A	2001
TCD 12	2003
TCU 12/24M	2003
TCU 12H	2004
TCU 24H	2003
TDA VC30	2008
TDA VC40	2009
TDA VC60	2008
TDR 1000	2001
TDR 1600	2001
TDR 3000	2001
TE 1 (1.gen)	31/12/2015
TE 10	2003
TE 10-A	2003
TE 12	2000
TE 12-S	2000
TE 14	2006

Tip Stroja	Godina
TE 17	1992
TE 22	2004
TE 22-P	1999
TE 24	2012
TE 42	2000
TE 52	2000
TE 504	2014
TE 54	2008
TE 5-A	2010
TE 60 (1. gen)	2000
TE 70-H	2000
TE 704	2014
TE 72	2004
TE 74	2011
TE 75	2014
TE 804	2012
TE 92	2002
TKD 3000	2001
TKD 5000	2001
TKT 1300	2001
TKT 1800	2001
TKT 2000	2001
TKT 2500	2001
TM 8	2000
TM 8-C	2000
TP 400	2000
TP 800	2001
TRH 1800	2000
TS 11	2000
TS 12	2000
UH 240-A	31/12/2015
VCU 40	31/07/2015
WFE 150	2008
WS 100	2004
WS 115	2004
WS 125	2004
WS 180	2004
WS 230	2004
WSA 8	2000
WSC 55 (1. gen)	2008
WSJ 110-EB	2011
WSJ 110-ET	2011
VSR 900	31/08/2015
WSR 1200PE	2010
WSC 265	2014
WVC 40-M	2009